





- *Optimal for Remote Sensing of AC Current Signals.*
- *Converts AC Current Signal to 0-10AC Volt Signal*
- *For use with Rectifier Type Analog Panel Meters or Digital Indicators.*
- *Perfect for Low Current Measurement Where a Donut Current Transformer would not Sense a Signal.*
- *UL Recognized*



These units are also about a third of the price compared to transmitters that amplify and isolate a current signal. Analog rectifier type meters can have custom dials installed to display the current value of the transformer. A digital display meter can be scaled to the current value easily, but a 20,000 ohm 1/2 watt shunt is required across the secondary of the current transformer for accuracy to be maintained.

## Dimension Drawing



## Ordering Information

Range	VA	Cat. Number
0-100mA	0.50	01295
0-500mA	0.53	01304
0-5Amp	0.40	01312
0-10Amp	0.50	01314
0-15Amp	0.37	01315
0-20Amp	0.48	01316
0-25Amp	0.53	01317
0-30Amp	0.37	01318
0-40Amp	0.42	01319
0-50Amp	0.54	01321

1. Accuracy readout of transmitter and meter @25°C with sinusoidal input is P/M 4% of F.S.
2. Operating temperature range is 140°F to -22°F (60°C to -30°C).