

0.750  
[ 19.0 ]


0.750  
[ 19.0 ]

TO APPLY MOUNT

- 1) CLEAN SURFACE WITH ISOPROPYL ALCOHOL.
- 2) REMOVE PROTECTIVE LINER.
- 3) PLACE IN DESIRED LOCATION.
- 4) APPLY PRESSURE TO MOUNT FOR 5 SECONDS.

**NOTES:**

- 
- 0.171±0.020  
[ 4.39±.508 ]
- 0.180  
[ 4.6 ]  
(REF)
- 0.065±.010  
[ 1.57±.254 ]
- ADHESIVE TAPE
- PRESSURE SENSITIVE TAPE  
THICK WITH PRO



(DIMENSIONS IN PARENTHESES ARE IN METRIC.)

G00239ER\_DC\_ABMM\_AT\_07

CORP. TINLEY PARK, ILLINOIS

UNLESS OTHERWISE SPECIFIED,  
DIMENSIONAL TOLERANCES ARE:  
(.X) ± ---- (.XXX) ± .020(.51)  
(.XX) ± .02(.51) ANGLES ± ----

	<b>MAT'Ls</b>
--	---------------

3 (ACRYLONITRILE BUTADIENE STYRENE)

**NONE**

GB0239ER

**DWG**  
**A**  
**SHEET**

7	11/18/04	JAD		UPDATE WEIGHT	GB0239ER	7				
REV	DATE	BY	CHK	DESCRIPTION	ECN	- R	CUST	SUP		